

Historical Record of all Retrofit Tether Anchor Parts

Retrofit TA parts were provided by most vehicle manufacturers for vehicles made in the 1990s. Manufacturers stopped making these parts for new vehicles in MY1999-2000, when FMVSS 225 established requirements for TAs to be factory installed. Over time, the stock of these parts has been depleted and not replenished; some parts remain in stock, but parts for some models are no longer available from a dealership.

Using the *LATCH Manual*: Use the current *LATCH Manual* (Appendix B and Chapter 6) when assisting caregivers with retrofitting TAs. It contains all the up-to-date information that vehicle manufacturers provide to SRN in order to help CPSTs guide caregivers. With respect to retrofitting TAs, manufacturers want CPSTs to know when parts are available, and to not encourage caregivers to seek parts that they can no longer supply. Therefore, manufacturers update their *LATCH Manual* information every two years, removing out-of-stock parts. Other related information is also in the current *LATCH Manual* (i.e., TA point location, the manufacturer's stance on using generic TAs, retrofit TA weight limits, the availability of a dealership installation program, and any other details provided by the manufacturer).

Using this online information: This historical record of all part numbers does not replace the information in the current *LATCH Manual*, but may be useful in certain situations, as explained here. By listing all retrofit TA part records, including parts that have been removed from the *LATCH Manual* due to being out-of-stock, it maintains a full account of all legitimate part numbers. Although some of these parts are no longer available from a dealership, SRN is motivated to make this information available to the public in case a CPST or caregiver finds a kit from a third-party and/or used parts provider. Of particular concern is that many unsafe alternative TAs are offered for sale these days, especially online. So, this record of all parts—both available and out-of-stock—is meant to assist people in confirming whether or not a part offered by a non-manufacturer source is one that came originally from the vehicle maker that's legitimately intended for use in their vehicle. If it is not, it should not be used!

[Acura](#)

[Audi](#)

[BMW](#)

[Buick](#)

[Cadillac](#)

[Chevrolet](#)

[Chrysler](#)

[Daewoo](#)

[Dodge](#)

[Eagle](#)

[Ferrari](#)

[Ford](#)

[Geo](#)

[GMC](#)

[Honda](#)

[Hyundai](#)

[Infiniti](#)

[Isuzu](#)

[Jaguar](#)

[Jeep](#)

[Kia](#)

[Land Rover](#)

[Lexus](#)

[Lincoln](#)

[Maserati](#)

[Mazda](#)

[Mercedes-Benz](#)

[Mercury](#)

[Mitsubishi](#)

[Nissan](#)

[Oldsmobile](#)

[Plymouth](#)

[Pontiac](#)

[Porsche](#)

[Saab](#)

[Saturn](#)

[Subaru](#)

[Suzuki](#)

[Toyota](#)

[Volkswagen](#)

[Volvo](#)

All Brands are listed alphabetically on the following pages.



ACURA

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.acura.com

Canada: www.acura.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
ALL MODELS NOT LISTED BELOW			Part Number: 82410-SE3-C01
NSX	2-door Coupe	02-05	Part Number: 82410-S84-C10
NSX-T	2-door Coupe	00-05	Part Number: 82410-S84-C10
SLX	4-door SUV	89-97	Part Number: No TA points are shown in owner's manual; the Isuzu Trooper and Acura SLX have the same interior body. The Isuzu part number is 8-97805-890-2.

AUDI

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.audiusa.com

Canada: www.audi.ca

- **Part numbers (apply to parts listed in the Additional Parts section, below):**
Pop Rivet: N905 763 01 (quantity 2 except as noted)
Spacer: 7M3 019 829
Threaded Plate: 444 819 649 (MY92-98 A6 Avant wagon and 100 Models wagon); 443 887 077C (all other models)
Plug: 321 867 164 (01C satin black)
Cap: 443 887 301 D 4PK

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			ANCHOR BRACKET	BOLT	ADDITIONAL PARTS AND NOTES (See bullet, above, for the part numbers not noted below)
80 Models 90 Models	4-door	88-95	443 887 269	N010 240 41	Additional Parts: Pop Rivet, Spacer; Threaded Plate, Plug, and Cap.
100 Models	4-door Sedan (not wagon)	89-91	443 887 269	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, Plug, and Cap.
		92-97	445 887 267B		Additional Parts: Pop Rivet, Spacer, Threaded Plate, and Cap.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			ANCHOR BRACKET	BOLT	ADDITIONAL PARTS AND NOTES (See bullet, above, for the part numbers not noted below)
100 Models	4-door Wagon	92-98	445 887 267B	N 010 239 29	Additional Parts: Threaded Plate; Hex Nut, N 010 008 40; Washer, contact an Audi dealership for the part number. Installation Note: Some vehicles do not have the welded TA points. In these cases, retrofit TAs cannot be installed.
200 Models	4-door Sedan (not wagon)	89-91	443 887 269	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, Plug, and Cap.
		92-97	445 887 267B		Additional Parts: Pop Rivet, Spacer, Threaded Plate, and Cap.
4000S	4-door Sedan	08/79-87	443 887 269	N010 240 41	Additional Parts: Cap Installation Note: 08/79-10/85 vehicles require installation of a mounting support, see an Audi dealer.
4000S QUATTRO	4-door Sedan	08/85-87	443 887 269	N010 240 41	Additional Parts: Cap Installation Note: 08/85-10/85 vehicles require installation of a mounting support, see an Audi dealer.
5000 AVANT	4-door Sedan	10/85-88	443 887 267B	N10668401	
5000S, CS, CD, & TURBO	4-door Sedan	10/82-88	443 887 269	N010 240 41	Additional Parts: Cap and Nut, N 010 008 40.
A4	4-door Sedan	96-98	443 887 269	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, Plug, and Cap.
		99			Additional Parts: Pop Rivet, Spacer, Threaded Plate, and Cap.
	4-door Wagon	98-Early-99	443 887 269	N010 240 41	Additional Parts: Cap and Spacer Sleeve, 7H5019825. Installation Note: MY98 and some MY99 require seatback change when installing TAs; contact an Audi dealership for details of Technical Service Bulletin 0101.
		Late-99		N010 240 22	
A6	4-door Sedan	92-97	445 887 267B	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, and Cap.
		98-99	443 887 269		
A6 AVANT	4-door Wagon	92-98	443 887 267B	N010 239 29	Additional Parts: Threaded Plate; Hex Nut, N 010 008 40; Washer, contact an Audi dealership for the part number. Installation Note: Some vehicles do not have the welded TA points. In these cases, retrofit TAs cannot be installed.
		98-99	443 887 269	N010 241 23	Additional Parts: Pop Rivet (quantity 1), Spacer, Threaded Plate, and Cap.

Find TA point locations/descriptions in a model's *LATCH Manual Appendix B* listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			ANCHOR BRACKET	BOLT	ADDITIONAL PARTS AND NOTES (See bullet, above, for the part numbers not noted below)
A8	4-door Sedan	97-98	443 887 269	N 100 632 05 (center position only)	Additional Parts: Pop Rivet, Spacer, and Cap. Part Numbers: Contact an Audi dealership for the bracket assembly part number.
		99	443 887 269	N 100 632 05	Additional Parts: Pop Rivet, Spacer, and Cap. Part Numbers: Contact an Audi dealership for the bracket assembly and bolts part number.
COUPE GT/ QUATTRO Type 857	2-door Coupe	86	443 887 269	N010 240 41	Additional Parts: Cap
COUPE QUATTRO	2-door Coupe	90-91		N010 247 8	Additional Parts, Center: Anchor Strap, 895 887 267A; Spacer; Washer, N901 791 03. Additional Parts, Outboard: Anchor Strap, 895 887 267A; Spacer; Reinforcement Plate, 171 861 641; Belt Guide, 895 887 827 01C; Screw, N014 144 4 (2 required); Washer, N901 791 02.
S4 / S6	4-door Sedan	92-97	445 887 267B	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, and Cap.
V8 QUATTRO	4-door Sedan	94	443 887 269	N010 240 41	Additional Parts: Pop Rivet, Spacer, Threaded Plate, Plug, and Cap.

BMW

Although retrofit TA parts were available for some pre-MY00 vehicles, part numbers were not reported to SRN. See a dealership and/or the owner's manual (under "child restraints"). Some parts may no longer be in stock.

U.S.: www.bmwusa.com

Canada: www.bmw.ca

BUICK

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Buick (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.buick.com

Canada: www.buick.ca

CADILLAC

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Cadillac (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.cadillac.com

Canada: www.cadillaccanada.ca

Find TA point locations/descriptions in a model's *LATCH Manual Appendix B* listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

CHEVROLET

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Chevy (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.chevrolet.com

Canada: www.chevrolet.ca

CHRYSLER

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. FCA honors service bulletin #23-014-15. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.chrysler.com

Canada: www.chrysler.ca

MODEL	BODY	YEAR	TA RETROFIT PARTS
300M	4-door Sedan	99	Part Number: 04519077AB
CIRRUS	4-door Sedan	95-99	Part Number: 04519077AB
CONCORDE	4-door Sedan	93-99	Part Number: 04519077AB
CONQUEST	2-door	87-89	Part Number: MB597261
IMPERIAL	4-door	90-93	Part Number: 04519071AC
LEBARON	4-door Sedan	89-94	Part Number: 04519071AC
	2-door Coupe	89-93	Part Number: 04519077AB
LEBARON GTS	4-door Sedan	85-89	Part Number, Center: 04519076AB Part Number, Outboard: 05003422AC
LHS	4-door Sedan	94-97	Part Number, Center: 04519077AB Part Number, Outboard: 05017645AA
		99	Part Number: 04519077AB
NEW YORKER	4-door Sedan	94-97	Part Number, Center: 04519077AB Part Number, Outboard: 05017645AA
NEW YORKER 5th AVENUE	4-door Sedan	89	Part Number: 04519077AB
		90-93	Part Number: 04519071AC

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT PARTS
NEW YORKER / LANDAU	4-door Sedan	89-93	Part Number, Center: 04519073AB Part Number, Outboard: 04519072AB
SEBRING	2-door Coupe	95-99	Part Number, Center: MB597261 Part Number, Outboard: MB612814
TOWN & COUNTRY	Minivan (NOT cargo van)	89-95	Part Number: 05017529AB
		96-00	Part Number, 2nd Row: 04864118AB Part Number, 3rd Row: 05018506AA
		02-07	Part Number, 3rd Row Full Bench Outboard: 05012007AB MY05-07: Some vehicles have optional Stow-and-Go Seating or a split bench seat; this retrofit TA part is NOT for these vehicles.
VOYAGER	Minivan (NOT cargo van)	02-05	Part Number, 3rd Row Full Bench Outboard: 05012007AB MY05: Some vehicles have optional Stow-and-Go Seating or a split bench seat; this retrofit TA part is NOT for these vehicles.

DAEWOO

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Daewoo (General Motors) no longer honors Service Bulletin #99-09-40-0048.

MODEL	BODY	YEAR	TA RETROFIT PARTS	
			ANCHOR	COVER
LANOS	2-door HB	99	96341705	96341702 (outboard-behind-driver position), 96341703 (outboard-behind-passenger position), 96341704 (center position)
	4-door Sedan	99	96345879 (center), 96342131 (outboard)	96341701
LEGANZA	4-door Sedan	99	96342229 (center), 96342230 (outboard)	96342233 (grey), 96342232 (beige)
NUBIRA	4-door Sedan	99	96216109	96342660 (grey), 96342261 (beige)
	4-door HB	99	96216109	96341701
	4-door Wagon	99	96341742	96342660 (grey), 96342261 (beige)

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

DODGE

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. FCA honors service bulletin #23-014-15. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.dodge.com

Canada: www.chrysler.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
ARIES	4-door Sedan	89-90	Part Number: 04519077AB
AVENGER	2-door Coupe	95-99	Part Number, Center: MB597261 Part Number, Outboard: MB612814
CARAVAN / GRAND CARAVAN	Minivan (NOT cargo van)	89-95	Part Number: 05017529AB
		96-00	Part Number, 2nd Row: 04864118AB Part Number, 3rd Row: 05018506AA
		02-07	Part Number, 3rd Row Full Bench Outboard: 05012007AB MY05-07: Some vehicles have optional Stow-and-Go Seating or a split bench seat; this retrofit TA part is NOT for these vehicles.
COLT	2-door	89-92	Part Number, Center: MB865730 Part Number, Outboard: MB597261
		93-94	Part Number: MB597261
	4-door	89-92	Part Number, Center: MB597261 Part Number, Outboard: MB612814
		93-94	Part Number: MB865730
COLT VISTA	2-door HB	91-95	Part Number: MB583400
DAKOTA	Pickup: Regular Cab (no rear doors)	88-99	Part Number: 05014765AA
		00	Part Number: 05017683AC
	Pickup: Club Cab	00	Part Number: 05016572AD Model Clarification: This listing applies to the 2-door Extended Cab with rear seats.
Pickup: Quad Cab	00	Part Number: 05016573AA Model Clarification: This listing applies to the 4-door Extended Cab with rear seats.	
DAYTONA	2-door	89-90	Part Number: 05003422AC
		91-94	Part Number: 04519074AB
DURANGO	4-door SUV	98-00	Part Number, 60/40-Split Seat: 05015403AA Part Number, 40/20/40-Split Seat: 05012007AB

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
DYNASTY	4-door	89-93	Part Number, Center: 04519072AB Part Number, Outboard: 04519072AB
INTREPID	4-door Sedan	93-99	Part Numbers: 04519077AB
LANCER	4-door HB	89	Part Number, Center: 04519076AB Part Number, Outboard: 05003422AC
MONACO	4-door	89-92	Part Numbers: 04519077AB
NEON	2- or 4-door	95-99	Part Number: 05017563AC
OMNI	2-door HB	89-90	Part Number, Center: 04519081AB Part Number, Outboard: 04519080AB
RAM 1500 / 2500 / 3500	Pickup: Regular Cab (no rear doors)	94–Early-01	Part Number: 05017032AB Note: This part is only for vehicles manufactured prior to 9/20/2000, the date TAs began being installed.
RAM WAGON	Wagon	89-00	Part Number: 04358469AB
SHADOW	2- or 4-door HB	89-94	Part Number: 04519292AB
SPIRIT	4-door	89-95	Part Number: 04519071AC
STEALTH	2-door Coupe	92-95	Part Number: MB597261
STRATUS	4-door Sedan	95-99	Part Numbers: 04519077AB
VIPER	2-door Coupe or Convertible	96-99	Part Number: 04883004AB

EAGLE

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. The part numbers beginning with "MB" were previously available through Mitsubishi. FCA honors service bulletin #23-014-15. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.chrysler.com

Canada: www.chrysler.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
PREMIER	4D Sedan	89-92	Part Number: 04519077AB

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
SUMMIT	4-door Sedan	89-92	Part Number, Center: MB597261 Part Number, Outboard: MB612814
		93-96	Part Number: MB865730
	2-door Coupe	89-92	Part Number, Center: MB865730 Part Number, Outboard: MB612814
		93-96	Part Number: MB597261
	Wagon	92-95	Part Number: MB583400
TALON	2-door Coupe	90-94	Part Numbers: MB590094, anchor; MF140227, bolt; MB593349, bracket (outboard-behind-driver position); MB593350 bracket (outboard-behind-passenger position)
		95-98	Part Number: MB583400
VISION	4-door Sedan	93-97	Part Number: 04519077AB

FERRARI

Although retrofit TA parts were available for some pre-MY00 vehicles, part numbers were not reported to SRN. Contact a dealership for details. Some parts may no longer remain in stock.

U.S.: www.ferrariworld.com or www.ferrariusa.com

FORD

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. The base part number for a Ford retrofit tether anchor kit is 613D74. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.ford.com

Canada: www.ford.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
AEROSTAR	Minivan	87-91	Part Number: Use a tether anchor kit provided by a CR manufacturer.
		92-97	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Part Description: "CSS Tether Strap Anchor Kit," 8-mm bolt, plate, weld nut bracket, and thread lock.
ASPIRE	2- or 4-door HB	94-97	Part Number: Previously F4BZ 61613D74-B; contact a Ford dealership to verify the part number.
BRONCO	2-door SUV	85-91	Part Number: Use a tether anchor kit provided by a CR manufacturer.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
BRONCO	2-door SUV	92-96	Part Number, Front Passenger Seat: Previously F2TZ 78613D74-A; contact a Ford dealership to verify the part number. Part Number, Outboard: Previously F2TZ 98613D74-A; contact a Ford dealership to verify the part number.
BRONCO II	2-door SUV	85-90	Part Number: Use a tether anchor kit provided by a CR manufacturer.
CONTOUR	4-door Sedan	95-00	Part Number: F5RZ 54613D74-A Part Description: "Tether Belt," 8-mm bolt, plate, washer, and retaining nut.
CROWN VICTORIA	4-door Sedan	89-92	Part Number: F13Z 54613D74-A Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
		93-99	Part Number: F3LB-63613D74-A (previously F3LY-63613D74-A) Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
	4-door Wagon	89-91	Part Number: F13Z 54613D74-A Part Description: "Safety Belt TA Kit," 8-mm bolt and plate.
ECONOLINE E150 thru E450	2-passenger Delivery Van	85-91	Part Number: Use a tether anchor kit provided by a CR manufacturer.
		92-96	Part Number: Previously F7UZ 5613- D74-AA; contact a Ford dealership to verify the part number.
	7-passenger Club Wagon	85-91	Part Number: Use a tether anchor kit provided by a CR manufacturer.
		92-00	Part Number, Front Passenger Seat: Previously F7UZ 5613-D74-AA; contact a Ford dealership to verify the part number. Part Number, 2nd and 3rd Row: Previously F7UZ 5613D74-AA; contact a Ford dealership to verify the part number. Installation Note, 2nd and 3rd Row: Flip bench seat forward to install; TA plate opening faces rear of vehicle.
ESCORT	4-door Sedan	91-93	Part Number: F1KY 54613D74-A Part Description: "TA Kit," All-in-one 8-mm bolt and spacers. Installation Note: Outboard-Behind-Driver Position: Use four spacers and bolt. Installation Note: Center Position: Use two spacers and bolt.
		94-96	Part Number: F4KY 54613D74-A Part Description: "TA Kit," All-in-one 8-mm bolt and spacers. Installation Note: Use bolt and either two spacers (center position) or four spacers (outboard-behind-driver position).
		97	Part Number: F7CZ 54613D74-AD Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacers.
		98-99	Part Number: F8CZ 63613D74-AA Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacers.
	2- or 4-door HB	89-90	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Part Description: "Tether Strap Anchor Kit," 8-mm bolt, plate, and weld nut bracket. Installation Note: To install TA, remove rear-lower-back trim panel in cargo area and the sealant that covers the weld nuts. Then, cut out marked hole in trim panel and reinstall. TA plate hole faces upward.
		91-96	Part Number: Previously F4CZ 58613D74-A; contact a Ford dealership to verify the part number.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
ESCORT	4-door Wagon	85-90	Part Number: F13Z 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut. Installation Note: To install TA, remove rear-lower-back trim panel in cargo area and the sealant that covers the weld nuts. Then, cut out marked hole in trim panel and reinstall. TA plate hole faces upward.
		91-93	Part Number: F4CZ 74613D74-A
		94-97	Part Number: F7CZ 74613D74-A
		98-99	Part Number: F8CZ 74613D74-AA Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacers.
ESCORT ZX2	2-door Coupe	98-99	Part Number: F8CZ 63613D74-AA Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacers.
EXPEDITION	4-door SUV	97-99	Part Number: Previously F75Z 8613D74-AA; contact a Ford dealership to verify the part number.
EXPLORER	4-door SUV	91-99	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Part Description: "Tether Strap Anchor Kit," 8-mm bolt, plate, weld nut bracket, & tube of thread lock.
EXPLORER SPORT	2-door SUV	91-99	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Part Description: "Tether Strap Anchor Kit," 8-mm bolt, plate, weld nut bracket, & tube of thread lock. Installation Note: To install TA, remove rear floor scuff plate and fold back carpet, then lift filler panel and lower spare tire.
F-150	Pickup: All Cabs (2-door)	85-91	Part Number: E5TZ-15613D20-A
	Pickup: Regular Cab (no rear seats)	97-99	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA)
	Pickup: Super Cab	92-99	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Model Clarification: This listing applies to the Super Cab model without side-facing seats.
		92-96	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Model Clarification: This listing applies to the Super Cab model with side-facing seats.
F-250	Pickup: All Cabs (2-door)	85-91	Part Number: E5TZ-15613D20-A
F-250 HD & F-250 LD	Pickup: Extended Cab	92-96	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Model Clarification: This listing applies to the Extended Cab, Extended Cab with side-facing seats, and Crew Cab models.
F250 SUPER DUTY	Pickup: Super Cab	99	Part Number: Contact a Ford dealership for the part number.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
F250 SUPER DUTY	Pickup: All Cabs	00	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Installation Note, Super Cab: See the current <i>LATCH Manual</i> for the installation instructions that replace the ones that come with the retrofit kit. Model Clarification: This listing applies to the Regular Cab, Super Cab with no rear seats, Super Cab, and Crew Cab models.
F-350	Pickup: All Cabs (2-door)	85-91	Part Number: E5TZ-15613D20-A
F-350 HD	Pickup: All Cabs	96	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Model Clarification: This listing applies to the Extended Cab, Extended Cab with side-facing seats, and Crew Cab models.
		97	Part Number: E5TZ 15613D20-A Model Clarification: This listing applies to the Extended Cab, Extended Cab with side-facing seats, and Crew Cab models.
F-350, F-450 & F-550 SUPER DUTY	Pickup: All Cabs	99-00	Part Number: F85B 15613D74-AB (previously F85Z 15613D74-AA) Model Clarification: This listing applies to the Regular Cab, Super Cab with no rear seats, Super Cab, and Crew Cab models.
FESTIVA	2-door HB	89-93	Part Number: F3BZ 61613D74-A
MUSTANG	2-door HB	89-92	Part Number: F13Z 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and retaining nut.
		93	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
	2-door Coupe	89-92	Part Number: F13Z 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and retaining nut.
		93	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Tether Belt Anchor Kit, 8-mm bolt, plate, washer, and retaining nut.
		94-99	Part Number: F4ZZ 63613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, and retaining nut bracket. Installation Note: Bolt is threaded from underneath, up through retaining nut bracket.
	2-door Convertible	94-99	Part Number: F4ZZ 63613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt and plate.
PROBE	2-door HB	90-97	Part Number: F42Z 61613D74-AA
RANGER	Pickup: Regular Cab (2-doors)	85-00	Part Number: E5TZ 15613D20-A Part Description: "Seat Tether Bracket Kit," 8-mm bolt, plate, and weld nut bracket.
	Pickup: Super Cab	86-00	Part Number: E6TZ13613D20-A Part Description: "Seat Tether Bracket Kit," 8-mm bolt, plate, and weld nut bracket. Installation Note: To install TA, remove trim panel, cut out hole and reinstall. Model Clarification: This listing applies to the Super Cab with and without rear seats.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
TAURUS	4-door Sedan	86-92	Part Number: F13Z 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
		93-95	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
		96-99	Part Number: F6DZ 54613D74-A Part Description: "Tether Strap Anchor Kit," 8-mm bolt, template, plate, and bracket with weld nut.
	Wagon	89-95	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Canada: Some models sold in Canada have TAs; the part number above is for vehicles sold without TAs. Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and support bracket.
TEMPO	2- door Coupe and 4-door Sedan	85-92	Part Number: F13Z 54613D74-A Part Description: "Tether Anchor Kit," 8-mm bolt, plate, washer, and nut.
	4-door Sedan	93-94	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Tether Anchor Kit," 8-mm bolt, plate, washer, and nut.
THUNDER-BIRD	2-door	89-92	Part Number: F13Z 54613D74-A Part Description: "Safety Belt Tether Anchor Kit," 8-mm bolt, plate, washer, and nut. Installation Note: To install, lower electrical panel inside trunk.
		93-97	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Safety Belt Tether Anchor Kit," 8-mm bolt, plate, washer, and nut. Installation Note: To install, lower electrical panel inside trunk.
WINDSTAR	Minivan	95-98	Part Number: YF2Z-15613D74-A

GEO

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Geo (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.chevrolet.com

GMC

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GMC dealership. Also, GMC (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.gmc.com

Canada: www.gmccanada.ca

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

HONDA

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.honda.com

Canada: www.honda.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
ALL MODELS NOT LISTED BELOW			Part Number: 82410-SE3-C01
EV PLUS	2-door Electric	-99	Installation Note: TA retrofit is not an option during these model years.
ODYSSEY	Minivan	99	Part Number and Name: 82410-SX0-000CH; "TA snap hook" Installation Note: The TA snap hook can be attached to the unused anchoring bar for the moveable 2nd row captain's chair in order to create a 2nd row TA.

HYUNDAI

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.hyundaiusa.com

Canada: www.hyundaicanada.com

MODEL	BODY	YEAR	TA RETROFIT NOTES
ACCENT	4-door Sedan	95-99	Part Number: 89850-23300
	2-door HB	95-99	Part Number: 89850-23100
ELANTRA	4-door Sedan	92-99	Part Number: 89850-23300
	Wagon	96-99	Part Number: 89850-23100
EXCEL	2- or 4-door HB	87-89	Part Number: 89850-23100
		90-94	Part Number: 89850-23300
	4-door Sedan	87-94	Part Number: 89850-23300
SCOUPE	2-door Coupe	91-95	Part Number: 89850-23300
SONATA	4-door Sedan	89-90	Part Number: 89850-23300
TIBURON	Coupe	97-99	Part Number: 89850-23100

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

INFINITI

Pre-MY00 vehicles use part number #88894-89900. Some parts may no longer remain in stock.

U.S.: www.infinitiusa.com

Canada: www.infiniti.ca

ISUZU

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a service facility or the current *LATCH Manual*.

U.S.: www.isuzu.com

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			PART NUMBER	PART NAME	
AMIGO	2-door SUV	91-94	8-97025-763-3	"Child Seat Anchor Kit"	
		98-00	8-97135-900-0		
AXIOM	4-door SUV	02-04	8-97248-080-1		
HOMBRE	Pickup: Regular and Space Cab (no rear seats)	96-00	Contact an Isuzu dealership for the part number.		
OASIS	4-door Minivan	96-99	5-86205-820-0		
RODEO	4-door SUV	91-97	8-97025-763-3		
		98-00	8-97135-900-0		
		01-04	8-97248-080-1		
RODEO SPORT	2-door SUV	01-03	8-97248-080-1		Contact an Isuzu dealership for the part name.
TROOPER	4-door SUV	92-00	8-97805-890-2		
		01-02	8-97220-336-0		
VEHI-CROSS	2-door SUV	99-00	8-97805-890-2		

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

JAGUAR

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.jaguarusa.com

Canada: www.jaguar.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			RETROFIT TA KIT PART NUMBER	BOLT SIZE IN KIT	ADDITIONAL PARTS
XJ SERIES	4-door Sedan	94	BEC 12556	5/16-inch bolt	
		95-96	HJA2100AA	5/16-inch bolt	
		97-99	HJA2100AA	8mm bolt	
XJS	2-door Coupe	93-96	BEC 12555	5/16-inch bolt	
	2-door Convertible	93-96			Installation Note: TA retrofit is not an option for this version.
XK SERIES	2-door Coupe	97-99	HJA2100AA	8mm bolt	Also requires additional support bracket (6 parts): HJA2106AA (Anchor Tower), HJD2105AA (Plate Mounting), and four of part FN106041 (M6 Flange Nuts).
	2-door Convertible	-00			Installation Note: TA retrofit is not an option for this version.

JEEP

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. FCA honors service bulletin #23-014-15. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.jeep.com

Canada: www.jeep.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES	
			CENTER POSITION	OUTBOARD POSITION(S)
CHEROKEE	4-door SUV	89-99	Installation Note: TA retrofit is not an option in this position.	Part Number: 05003422AC
		00	Installation Note: TA retrofit is not an option in this position.	Part Number: 05066385AA
GRAND CHEROKEE	4-door SUV	93-98	Part Number: 04728952AB	Installation Note: TA retrofit is not an option in these position(s).

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES	
			CENTER POSITION	OUTBOARD POSITION(S)
GRAND CHEROKEE	4-door SUV	99-00	Installation Note: TA retrofit is not an option in this position.	Canada—Part Number: 05016871AA (camel trim). Previously 05016873AA (taupe trim); contact a Jeep dealership to verify the part number. U.S.—Part Number: 05016870AA (taupe trim)
GRAND WAGONEER	4-door SUV	85-92	Installation Note: TA retrofit is not an option during these model years.	
		93-98	Part Number: 04728952AB	Installation Note: TA retrofit is not an option in these position(s).
WAGONEER	4-door SUV	85-90	Part Number: Previously 04519075; contact a Jeep dealership to verify the part number.	Part Number: Previously 04519075; contact a Jeep dealership to verify the part number.
WRANGLER	2-door SUV	87-99	Installation Note: TA retrofit is not an option during these model years.	
		00	Installation Note: TA retrofit is not an option in this position.	Part Number: 05066347AA

KIA

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.kia.com

Canada: www.kia.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
SEPHIA and SEPHIA LS	4-door Sedan	94- Early-99	Installation Note: TA retrofit is not an option during these model years.
		Late-99	Part Numbers: OK28E57-77-ZA and OK28E577A6 (cover)
SPORTAGE	4-door SUV	94-00	Part Number, Canada: Some models have a TA retrofit kit in the glove box. Part Number, United States: TA retrofit is not an option for these vehicles
	2-door Semi-Convert. SUV	99	Installation Note: TA retrofit is not an option for this version.

LAND ROVER

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S. and Canada: www.landroverusa.com

Canada: www.landrover.ca

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES	
			PART NUMBER	PART NAME
DISCOVERY/ DISCOVERY SERIES II	5- or 7- passenger, 4-door SUV	94-99	LRN0449	Child Seat Tether Bracket
		99-00	LRN0449 EDV100460LUM	Child Seat Tether Bracket Rear Header Finisher (center position only)
RANGE ROVER	4-door SUV	96-99	AWR1365 AWR2591LUM BTR6681	Bracket Bracket Cover Trim Stud

LEXUS

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.lexus.com

Canada: www.lexuscanada.com

MODEL	BODY	YEAR	TA RETROFIT NOTES
ALL OTHER MODELS		79-99	Part Number: 73709-20010 Part Name: Bracket Sub-Assembly, Tether Anchor
ES 300	4-door Sedan	92-99	Part Number: 73709-12010
GS300	4-door Sedan	93-99	Part Number: Owner's manual states "CRS installation kit" is part #04731-22012 and the "Bolt" is part #91511-60830.
GS 400	4-door Sedan	98-99	Part Number: 73708-50020
LS 400	4-door	90-99	Part Number: Owner's manual states "CRS installation kit" is part #04731-22012 and the "Bolt" is part #91511-60830.
LX 450	SUV	96-97	Part Number: MY97 Owner's manual states "CRS installation kit" is part #04731-22012 and the "Bolt" is part #91511-60830.
RX 300	SUV	99-00	Part Number: 73709-12010
SC300 / 400	2-door Coupe	92-97	Part Number: MY92-96 Owner's manual states "CRS installation kit" is part #04731-22012 and the "Bolt" is part #91511-60830.
		98-00	Part Number: Contact a Lexus dealership for the part number. Part Availability: This part is not available from Lexus.

LINCOLN

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. The base part number for a Lincoln retrofit tether anchor kit is 613D74. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.lincoln.com

Canada: www.lincoln.ca

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
CONTINENTAL	4-door Sedan	89-92	Part Number: F13Z 54613D74-A Part Description: "CSS Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and retaining nut.
		93-94	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "CSS Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
		95-99	Part Number: Previously F50Y 54613D74-A; contact a Lincoln dealership to verify the part number. Part Description: "CSS Tether Belt Anchor Kit," Bezel /cover assemblies, anchor bracket, 8-mm bolts, and retaining screws.
MARK VII	2-door Coupe	89-92	Part Number: F13Z 54613D74-A Part Description: "CSS Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
MARK VIII	2-door Coupe	93-98	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "CSS Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
NAVIGATOR	4-door SUV	98-02	Part Number: Previously F75Z 8613D74-AA; contact a Lincoln dealership to verify the part number.
TOWN CAR	4-door Sedan	89-90	Part Number: F13Z 54613D74-A Part Description: "CSS Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
		91-99	Part Number: F1VY 54613D74-A

MASERATI

Although retrofit TA parts were available for some MY01 and older vehicles, part numbers were not reported to SRN. Contact a dealership for details. Some parts may no longer remain in stock.

U.S.: www.maserati.com

Canada: www.maserati.com

MAZDA

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.mazdausa.com

Canada: www.mazda.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
323	2-door HB	89	Part Number: BM91-57-77X (2-wheel drive), BN03-57-77X (4-wheel drive)
		90-94	Part Number: BR90-57-77XB
		95	Part Number: BC1B-57-77X
	4-door Wagon	89	Part Number: BP55-57-77X
	4D Sedan	89	Part Number: BN07-57-77X

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
626	4-door HB	90-92	Part Number: GJ37-57-77X
	4-door Sedan	89-92	Part Number: GJ30-57-77X
		93-97	Part Number: GA2K-57-77XA
		98-99	Part Number: GD7A-57-77X
929	4-door Sedan	89-91	Part Number: Contact a Mazda dealership for the part number.
		92-95	Part Number: HG31-57-77XA
B-SERIES	Pickup: All Cabs	94-00	Part Number: ZZM0-57-528 Model Clarification: This listing applies to the Regular Cab and Cab Plus.
MILLENIA	4-door Sedan	95-00	Part Number: TA02-57-77XB
MPV	Minivan	89-95	Part Number: LA01-57-77X
		96-98	Part Number: LB82-57-77X
		00	Part Number: LCY2-57-77XB-05 (Gray); LCY2-57-77XB-80 (Beige)
MX3	2-door HB	92-95	Part Number: Contact a Mazda dealership for the part number.
MX6	2-door Coupe	89-92	Part Number: GJ21-57-77X
		93-97	Part Number: GA2A-57-77XA
PROTEGE	4-door Sedan	90-94	Part Number: BR90-57-77XB
		95-98	Part Number: BC1N-57-77XA
		99	Part Number: BJOE-57-77XA
RX-7	2-door HB	89-92	Part Number: FC11-57-77X
		93-95	Part Number: FD01-57-77X

MERCEDES-BENZ

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.mbusa.com

Canada: www.mercedes-benz.ca

- **Pre-1983 models:** Use parts 100 99 104 40 (spacer) and 123 860 00 11 (screw plug) with a generic tether anchor kit (acquired from a CR manufacturer) that has a 5/16-inch bolt for models 230, 240D, 280CE, 280E, 280SL, 280SLC, 300 TURBO, 300CD, 300CD TURBO, 300D, 300SD TURBO, 300TD, 300TD TURBO, 350SL, 350SLC, 380SEC, 380SEL, 380SL, 380SLC, 450SL, 450SLC, and 500SL.

- **1984-1985 models:** Use part 100 99 104 40 (spacer) with a generic tether anchor kit (acquired from a CR manufacturer) that has a 5/16-inch bolt for models 190E, 190D, 300CD TURBO, 300D TURBO, 300SD TURBO, 300SDL TURBO, 300SE, 300SEL, 300TD TURBO, 350SDL TURBO, 380SE, 380SL, 420SEL, 500SL, 560SL, and S50SD TURBO.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

- **1986-1999 models:** Use part 100 99 104 40 (spacer) with a generic tether anchor kit (acquired from a CR manufacturer) that has a 5/16-inch bolt for models 190E, 190D, 260E, 300CD TURBO, 300CE, 300D, 300D TURBO, 300E, 300SD TURBO, 300SDL TURBO, 300SE, 300SEL, 300TD TURBO, 300TE, 350SDL TURBO, 380SE, 380SL, 400E, 420SEL, 500E, 500SL, 560SL, E300D, E320, E420, E500, and S50SD TURBO.

MERCURY

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. The base part number for a Mercury retrofit tether anchor kit is 613D74. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.mercuryvehicles.com

Canada: www.mercuryvehicles.com

MODEL	BODY	YEAR	TA RETROFIT NOTES
CAPRI	2-door Convertible	91-94	Part Number: F13Z 54613D74-A Installation Note: The 5/16" bolt and locking clip were in the glove box when the vehicle departed the factory.
COUGAR	2-door Coupe	89-92	Part Number: F13Z 54613D74-A Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
		93-97	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
	2-door HB	99	Part Number: F8RZ 63613D74-AA Part Description: "TA Kit," 8-mm bolt and plate. Installation Note: To install TA, snap out trim cover; plate protrudes through hole on rear trim cover.
GRAND MARQUIS	4-door Sedan	89-92	Part Number: F13Z 54613D74-A Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
		93-99	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Safety Belt TA Kit," 8-mm bolt, plate, washer, and nut.
	4-door Wagon	89-91	Part Number: F13Z 54613D74-A Part Description: "Safety Belt TA Kit," 8-mm bolt and plate.
MOUNTAINEER	4-door SUV	96-99	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Part Description: "Tether Strap Anchor Kit," 8-mm bolt, plate, weld nut bracket and tube of thread lock.
MYSTIQUE	4-door Sedan	95-00	Part Number: F5RZ 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate and retaining nut.
SABLE	4-door Sedan	86-92	Part Number: F13Z 54613D74-A Part Description: "Safety Belt Tether Anchor Kit," 8-mm bolt, plate, washer, and nut.
		93-95	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Safety Belt Tether Anchor Kit," 8-mm bolt, plate, washer, and nut.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
SABLE	4-door Sedan	96-99	Part Number: F6DZ 54613D74-A Part Description, Center: "Tether Belt Anchor Kit," 8-mm bolt, anchor bracket with weld nut, washer, and template. Part Description, Outboard: "Tether Belt Anchor Kit," 8-mm bolt, plate, nut, washer, and template.
	4-door Wagon	89-95	Part Number: F17B 78613D74-AB (previously F17Z 78613D74-A) Canada: Some models sold in Canada have TAs; the part number above is for vehicles sold without TAs. Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and support bracket.
TOPAZ	2- and 4-door	85-92	Part Number: F13Z 54613D74-A Part Description: "Tether Belt Anchor Kit," 8-mm bolt, plate, washer, and nut.
	4-door	93-94	Part Number: F3LB-63613D74-AA (previously F3LY-63613D74-A) Part Description: "Tether Anchor Kit," 8-mm bolt, plate, washer, and nut.
TRACER	4-door Sedan	91-93	Part Number: F1KY 54613D74-A Part Description: "Tether Anchor Kit," 8-mm bolt and spacers.
		94-96	Part Number: F4KY 54613D74-A Part Description: "Tether Anchor Kit," 8-mm bolt and spacers.
		97	Part Number: F7CZ 54613D74-AD Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacer.
TRACER	4-door Sedan	98-99	Part Number: F8CZ63613D74-AA Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacer.
	4-door Wagon	91-93	Part Number: F4CZ74613D74-A
		94-96	Part Number: F7CZ74613D74-A
		97	Part Number: Contact a Mercury (Ford) dealership for the part number.
	98-99	Part Number: F8CZ 74613D74-AA Part Description: "Tether Strap Anchor Kit," All-in-one 5/16" bolt and spacer.	
VILLAGER	Minivan	93-99	Part Number: F3XY12613D20-A Installation Note, 3rd Row: To install TA, cut open U-shaped perforated opening with utility knife, then remove installed bolt and install TA retrofit part.

MITSUBISHI

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.mitsucars.com

Canada: www.mitsubishi-motors.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
3000GT	2-door Coupe	91-99	Part Number: MB597261

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
CORDIA/ TREDIA	2-door HB	89-87	Installation Note: TA retrofit is not an option during these model years.
DIAMANTE	4-door Sedan	92-96	Part Number, Outboard: MB583401 Part Number, Center: MB583400.
		97-99	Part Number, Outboard: MB583401 Part Number, Center: MB583400
	4-door Wagon	93	Part Number, Outboard: MB583401 Part Number, Center: MB583400
ECLIPSE	2-door Coupe	90-94	Part Number: MB590094 Installation Note: Do not use a spacer.
		95-00	Part Number: MB583400.
EXPO	3-door Minivan	95	Part Number: MB597261
EXPO LRV	Minivan	92-94	Part Number: MB597261
GALANT	4-door Sedan	-87	Part Number: Contact a Mitsubishi dealership for the part number.
		88-93	Part Number: MB597261
		94-98	Part Numbers: MB597261 (center), MB612814 (outboard)
		99-00	Part Number: MB612814 MY00: Some vehicles are equipped with factory-installed TAs.
MIRAGE	4-door Sedan and 2-door Coupe	-92	Part Number: Contact a Mitsubishi dealership for the part number.
		93-99	Part Number: MB597261
MONTERO	4-door SUV	89-96	Installation Note: TA retrofit is not an option during these model years.
		97-00	Part Number: MB597261
MONTERO SPORT	4-door SUV	97-00	Part Number: MB597261
PRECIS	2-door HB	92-94	Part Number: Contact a Mitsubishi dealership for the part number.
SIGMA	4-door Sedan	88-90	Part Number: MB406896
TREDIA	4-door Sedan	83-88	Part Number: Contact a Mitsubishi dealership for the part number.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

NISSAN

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.nissanusa.com

Canada: www.nissan.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
ALL MODELS NOT LISTED BELOW		-99	Part Number: 88894-89900
ALTIMA	4-door Sedan	93-99	Part Number, U.S.: 88894-89900 Part Number, Canada: 88894-89902
FRONTIER	Pickup: All Cabs	97-00	Part Number, U.S.: 88894-89900 Part Number, Canada: 88894-89902 Model Clarification: This listing applies to the Regular Cab, King Cab with no seats, and Crew Cab models.
QUEST	Minivan	98-03	Part Number, U.S.: 88894-89900 Part Number, Canada: 88894-89902
STANZA	4-door Sedan	92	
XTERRA	4-door SUV	99-00	

OLDSMOBILE

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Oldsmobile (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.oldsmobile.com

PLYMOUTH

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. For some parts, the two-letter suffix in the part number has changed over time but the remaining part number is the same. The part numbers beginning with "MB" were previously available through Mitsubishi. FCA honors service bulletin #23-014-15. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.chrysler.com

Canada: www.chrysler.ca

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES
ACCLAIM	4-door Sedan	89-95	Part Number: 04519071AB
BREEZE	4-door Sedan	95-99	Part Number: 04519077AB
COLT	2-door	89-92	Part Numbers: MB865730 (center), MB597261 (outboard)
		93-94	Part Number: MB597261
	4-door	89-92	Part Numbers: MB597261 (center), MB612814 (outboard)
		93-94	Part Number: MB865730
COLT VISTA	Wagon	91-94	Part Number: MB583400
GRAN FURY	4-door Sedan	89	Part Number: 04519077AB
HORIZON	4-door Sedan	89-90	Part Number: 04519081AB
LASER	2-door Coupe	90-94	Part Numbers: MB590094, anchor; MB140227, bolt; MB593349, bracket (driver side); MB593350, bracket (passenger side).
NEON	2- or 4-door Sedan	95-99	Part Number: 05017563AC
PROWLER	2-door Convertible	97-99	Part Number: 05017570AA
RELIANT	4-door Sedan	89-90	Part Number: 04519077AB
SUNDANCE	2- or 4-door Sedan	89-94	Part Number: 04519292AB
VOYAGER/ GRAND VOYAGER	Minivan	89-95	Part Number: 05017529AB
		96-00	Part Numbers: 04864118AB (2 nd row); 05018506AA (3 rd row)

PONTIAC

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Pontiac (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: www.pontiac.com

Canada: www.gm.ca

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

PORSCHE

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.porsche.com/usa

Canada: www.porsche.com/canada

MODEL	BODY	YEAR	TA RETROFIT NOTES
911	2-door Sports Car	88-00	Part Number: Contact a Porsche dealership for the part number. Installation Note: This model uses the same part number as the 928 / 944 / 968 2-door sports car.
928 / 944 / 968	2-door Sports Car	88-95	Part Number: Contact a Porsche dealership for the part number. Installation Note: This model uses the same part number as the 911 2-door sports car.
BOXSTER	2-door Convertible	97-	Part Number, Canada: Contact a Porsche dealership for the part number. Installation Note, U.S.: TA retrofit is not an option in this model.

SAAB

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see the current *LATCH Manual*.

MODEL	BODY	YEAR	TA RETROFIT NOTES
900	4-door Sedan and 4-door HB and 2-door HB	-93	Part Numbers: Bracket, 9537606; Washer, 9593542
		94-98	Part Number: 4505467
	2-door Convertible	94-98	Part Number: 4505467
9000	4-door	-92	Part Numbers: Plate, 9653502; Rivet, 7972490; Washer, 9593542
		93-98	Part Number: 9593534
	4-door HB	93-98	Part Number: 4657094
9-3	All Models	99	Part Number, 4-door Sedan, 2- /4-door Sport Combi HB, and 2-door Convertible: 4505467 Model Clarification: This listing applies to the 4-door sedan, 2- or 4-door Sport Combi HB, and 2-door Convertible.
9-5	All Models	99- Early-00	Part Number: 5013560 Model Clarification: This listing applies to the 4-door sedan and 4-door wagon.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

SATURN

Although retrofit TA parts were available for some pre-MY00 vehicles, GM did not provide part numbers to SRN. For current availability of parts, contact a GM dealership. Also, Saturn (General Motors) no longer honors Service Bulletin #99-09-40-0048.

U.S.: <https://www.mycertifiedservice.comsaturn-service-repair.html>

Canada: www.gm.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES
S SERIES	2- or 3-door Coupe	91-99	Part Number: 21048010
	4-door Sedan	91-99	Part Number: 21048101
	4-door Wagon	91-99	Part Number: 21048023

SUBARU

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.subaru.com

Canada: www.subaru.ca

MODEL	BODY	YEAR	TA RETROFIT NOTES			
			PART NUMBER—BEIGE	PART NUMBER—BLUE	PART NUMBER—BLACK	PART NUMBER—GRAY
FORESTER	4-door Wagon	98-99	96030FC120			96030FC110
IMPREZA	4-door Sedan	93-99	96031FA000EM			96031FA000MJ
	2-door Coupe	95-99	96031FA000EM			96031FA000MJ
	4-door Wagon	93-99	96031FA010EM			96031FA010MJ
LEGACY	4-door Sedan	90-91	96031AA080EL	96031AA080BI		96031AA080LM
		92-94	96031AA080EM	96031AA080BK	96031AA080ML	96031AA080MJ
		95-99				96031AC000MU (dark gray) 96031AC000RA (red gray)

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES			
			PART NUMBER—BEIGE	PART NUMBER—BLUE	PART NUMBER—BLACK	PART NUMBER—GRAY
LEGACY	4-door Wagon	90-91	96031AA090EL	96031AA090BI		96031AA090LM
		92-94	96031AA090EM	96031AA090BK	96031AA080ML	96031AA090MJ
		95-99				96031AC070 (dark gray) 96031AC080 (red gray)
LEONE/ LOYALE	4-door Wagon	85-94		96031GA060BE		96031GA060LR
	2-door HB	86-89		96031GA060BE		96031GA060LR
LEONE/ LOYALE XT/ XT6	4-door Sedan	85-93		96031GA070BE		96031GA070LR
	2-door Coupe	85-91		96031GA070BE		96031GA070LR
SVX	2-door Coupe	92-97	96031PA030			96031PA000

SUZUKI

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.suzukiauto.com

Canada: www.suzuki.ca/auto

MODEL	BODY	YEAR	TA RETROFIT NOTES
ESTEEM	4-door Sedan	95-99	Part Numbers: 75481-70C00, 75484-70C00, 09103-08276 and 75485-50G00-T01
	4-door Wagon	98-99	Part Numbers: 75481-70C00, 09180-08208, and 09103-08337
		00	Installation Note: If the vehicle lacks a TA, contact a U.S. or Canadian Service Provider.
SIDEKICK	4-door SUV	96-97	Part Numbers: 75481-70C00, 75484-70C00, 09103-08276, and 75485-60A00
		98	Part Numbers: 75481-83370, 75484-70C00, 09103-08276, and 75485-60A00
SWIFT	4-door Sedan and 2-door HB	95-99	Part Numbers: 76292-60B10-6WV and 75480-60B00
VITARA / GRAND VITARA	2-door and 4-door SUV	98-99	Part Numbers: 75481-83370, 75484-70C00, 75486-65D00, and 75485-60A00-T01
		00	Part Numbers: 75481-70C00, 0910-08117, 75486-65D00, and 75485-60A00-T01
X-90	2-door SUV	96-98	Part Numbers: See a U.S. or Canadian Service Provider for the part number.

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

TOYOTA

Retrofit TA parts were available for some MY79-99 vehicles; the “Bracket Sub-Assembly, Tether Anchor” part number is 73709-20010. For current availability of this part, see a dealership or the current *LATCH Manual*.

U.S.: www.toyota.com

Canada: www.toyota.ca

VOLKSWAGEN

The following are all retrofit TA part numbers for the brand’s vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.vw.com

Canada: www.vw.ca

- **Part numbers (apply to parts listed in the Additional Parts section, below):**
Pop Rivet: N905 763 01 (quantity 2)
Plug: 321 867 164 01C
Cap: 443 887 301 D 4PK

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			ANCHOR BRACKET	BOLT	ADDITIONAL PARTS AND NOTES (See bullet, above, for the part numbers not noted below)
CABRIOLET	2-door Convertible	80-93	Universal anchor bracket acquired from a CR maker	N010 240 16	Additional Parts: Spacer, 803 019 825B; Washer, N015 401 3; and Nut, N 01100840.
EUROVAN	Van	92-99	445 887 267B	N989 108 01	Additional Parts: Anchor Plate, 703 858 773; Washer, N011 525 27; and Rivets, N016 199 2 (2 required). Model Clarification: This listing applies to Multi-Van (MV) versions, those with triple bench rear seat, and those with folding rear seat.
FOX	2- or 4-door HB	89-93	443 887 269	N010 340 4	Additional Parts: Cap; Nut, N011 008 46; Bushing; and Washer. Contact a Volkswagen dealership for the bushing and washer part number.
FOX WAGON	4-door	89-93	443 887 269;	N010 239 29	Additional Part: Cap
GOLF / GTI	2-door HB	88-89		N010 239 29	Additional Parts: Felt Strips, 533 863 288A; Bar Support, 176 857 875 (CDN); and Anchor Plate, 176 887 269 (CDN).
	4-door HB	88-92		N010 239 29	Additional Parts: Felt Strips, 533 863 288A; Bar Support, 176 857 875 (CDN); and Anchor Plate, 176 887 269 (CDN).
GOLF / GTI / RABBIT	2- or 4-door HB	93-98	443 887 269	N010 244 25	Additional Parts: Cap; Metal Bar, contact a Volkswagen dealership for the part number; Spacer, 7M3019 829; Bar Support (Driver side), 1H6 858 878; and Bar Support (Passenger side), 1H6 858 877.

Find TA point locations/descriptions in a model’s *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			ANCHOR BRACKET	BOLT	ADDITIONAL PARTS AND NOTES (See bullet, above, for the part numbers not noted below)
GOLF / GTI / RABBIT	2- or 4-door HB	Early-99	443 887 269	N010 241 23	Additional Parts: Cap; contact a Volkswagen dealership to verify the parts required for this model.
JETTA & JETTA (A3)	4-door	85-92	Universal anchor bracket acquired from a CR maker	Contact a Volkswagen dealership for part number.	Additional Parts: Spacer, 7H5019825; Washer, N0154018; and Nut, N011 008 40.
		93-99	443 887 269	N 989 108-01	Additional Parts: Pop Rivet; Cap; Spacer, 1H5 858 846; and Threaded Plate, N989 514 01.
JETTA (A4)	4-door Sedan	Early-99	1J0 858 849		Additional Parts: Pop Rivet; Plug; Cap, 1H0 887 301 01C/U71/Q70; and Speed Nut, N 989 514 01.
NEW BEETLE	2-door	98- Early-99	1J0 858 849	N100 632 05	Additional Parts: Cap, 1H0 887 301 01C/U71/Q70 and Washer, contact a Volkswagen dealership for the part number. Canada: Vehicles sold in Canada have <i>factory-installed</i> TAs.
PASSAT	4-door Sedan	92-97	443 887 269 Optional to use a universal anchor bracket acquired from a CR maker	N 010 244 25	Additional Parts: Cap; Washer, N011 670 26; and Nut, N011 008 40.
		98- Early-99	1J0 858 849		Additional Parts: Pop Rivet; Plug; Cover, 1H0 887 301 01C; Spacer, 1H5 858 846A; and Speed Nut, N989 514 01.
	Wagon	98- Early-99	443 887 269	N010 241 23	Additional Part: Cap
SCIROCOCO	2-door	82-88	Universal anchor bracket acquired from a CR maker	N010 244 25	Additional Parts: Spacer, 431 253 205 B; Washer, N011 670 26; and Nut, N011 008 46.
VANAGON	Van	81-91			Installation Note: TA retrofit is not an option during these model years.

VOLVO

The following are all retrofit TA part numbers for the brand's vehicles, as reported to SRN. Some parts may no longer remain in stock. For current availability of parts, see a dealership or the current *LATCH Manual*.

U.S.: www.volvocars.us

Canada: www.volvocanada.com

Find TA point locations/descriptions in a model's *LATCH Manual* Appendix B listing. See Ch. 6 of the *LATCH Manual* for brand- and model-specific retrofitting information.

KEY: TA Retrofit—Consumer- or dealer-installed tether anchor TA—Factory-installed tether anchor TA point—Designated retrofit TA location MY—Model year CR—Child restraint

MODEL	BODY	YEAR	TA RETROFIT NOTES		
			PART NAME	PART NUMBER	ADDITIONAL INFORMATION
240	4-door Wagon	78-88			Part Number: Contact a Volvo dealership for the part number.
		89-93	"Tether Hook"	3525051-3	
240 / 260	2- or 4-door Sedan	78-93	"Anchor Plate Tether Hook Kit"	3525050-5	
700 series	4-door	85-92	"Tether Hook"	6812131	
	4-door Wagon	85-88	"Tether Hook and Strap"	3525053-9	Installation Note: Strap will extend anchor bracket from inside spare tire storage area, bringing it closer to the vehicle seat.
		89-	"Tether Hook"	6812131	Installation Note: Remove plastic screw from weld nut to add TA.
740 / 760	4-door Sedan	-88			Part Number: Contact a Volvo dealership for the part number.
		89-92	"Tether Hook"	6812131	Part Number: Contact a Volvo dealership to verify the parts required for this model.
850	4-door Sedan	93-97	"Tether Hook"	9475763	
	4-door Wagon	94-97	"Tether Hook"	9138222-6, 9475766-3, 986415-0, and 979932-1	
900 series	4-door Wagon	85-88	"Tether Hook and Strap"	3525053-9	Installation Note: Strap will extend anchor bracket from inside spare tire storage area, bringing it closer to the vehicle seat.
		89-	"Tether Hook"	6812131	Installation Note: Remove plastic screw from weld nut to add TA.
940 / 960	4-door Sedan	91-97	"Tether Hook"	3548778-4	
	4-door Wagon	91-93	"Tether Hook"	3548778-4	
C70	2-door Coupe	98- Early-00	"Tether Hook"	9475768-9	
	2-door Convertible	98-02			Installation Note: TA retrofit is not an option during these model years.
S70	4-door Sedan	97- Early-00	"Tether Hook"	9475763-0	
S80	4-door Sedan	99- Early-00	"Tether Hook"	39965108-2	
S90	4-door Sedan	97-98	"Tether Hook"	3548778-4	
V70	4-door Wagon	97- Early-00	"Tether Hook"	9138222-6, 9475766-3, 986415-0, and 979932-1	
V90	4-door Wagon	97-98	"Tether Hook"	6812131	