

LATCH Manual Update Related to the Chevrolet Equinox and GMC Terrain

2023-2024 LM Updates Page, www.saferidenews.com

Note: If you are updating more than one *LATCH Manual*, see page 2.

Chevrolet
Equinox

(3) TAs TAs on backs of seats

Cargo Cover: If removed for TA installation, place in storage location under load floor.

Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry).

Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A Chevrolet dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.

GMC
Terrain

(3) TAs TAs on backs of seats

Cargo Cover: If removed for TA installation, place in storage location under load floor.

Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry).

Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A GMC dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.

LATCH Manual Update Related to the Chevrolet Equinox and GMC Terrain

2023-2024 LM Updates Page, www.saferidenews.com

Note: If you are updating only one *LATCH Manual*, see page 1.

	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A Chevrolet dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>
Chevrolet Equinox	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A Chevrolet dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>
	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A Chevrolet dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>
	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A GMC dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>
GMC Terrain	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A GMC dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>
	<p>(3) TAs on backs of seats Cargo Cover: If removed for TA installation, place in storage location under load floor. Front Seat Belt: See “Dynamic latchplate” in the bullet section (top of this entry). Recall, MY20-23: The LAs of vehicles made 6/02/2020-3/19/2023 may have excessive coating on them that may interfere with CR installation. A GMC dealer will inspect and, if necessary, repair the lower anchor bars. NHTSA Campaign #23V-339.</p>