

## LATCH Manual Updates • 2021-2022

Updates to the 2021 *LATCH Manual* are listed by Chapter/Appendix and page number, below. Changed text is struck-through and the updated text is given in red. A PDF version is available for longer passages in order to provide a printer-friendly version that can be cut/pasted into your 2021 *LATCH Manual*, if desired.



as of \*\*/\*\*/2021

Update(s) included in the most recent posting are marked **NEW**.

If you'd like to be notified by e-mail when updates are made to this page, select "Sign Up for Email Updates" from the Quick Links (at the bottom left of the [www.saferideneews.com](http://www.saferideneews.com) homepage) and follow the prompts.

**Navigation options: Scroll down to see all of the posted updates in the order they appear in the *LATCH Manual*, or select from the list below to jump to a particular Chapter/Appendix that has been updated (as indicated by colored font).**

Glossary

Chapter 1

Chapter 2

Chapter 3

Chapter 4

Chapter 5

Chapter 6

Chapter 7

Chapter 8

[Appendix A](#)

[Appendix B](#)

Appendix C

Index

### Updates to Appendix A:



as of 02/09/2021

#### **Page A-65, Simple Parenting**

REASON FOR UPDATE: Error in distributor name.

Revise the following information by replacing the struck-out text with the text in red.

#### **Simple Parenting**

Distributed by ~~Happy-Kidz~~ **SP Distribution, LLC**

***Updates continued on next page.***

## LATCH Manual Updates • 2021-2022

### Updates to Appendix B:



as of 02/09/2021

#### Page B-128, Jeep

REASON FOR UPDATE: Clarification that the *LATCH Manual* information is correct by adding an Owner's Manual Correction note.

[Click here](#) for a PDF that has been formatted so it can be printed, cut out, and attached to pages B-128.

Please add the note in red.

COMMAN- DER 7-passenger SUV	06-10	LATCH	(2) LATCH	N/A	None	(3) TAs on backs of seats. To tether in the 2 <sup>nd</sup> row, route tether over the center of the head restraint, if present. If head restraints interfere with proper placement of CR, vehicle seatback may be reclined slightly to achieve an acceptable CR position. <b>Maximum Child Weight For Using TAs:</b> When a seat belt is used to install the CR, the tether may be attached at all weights recommended by the CR manufacturer. <b>Owner's Manual Correction:</b> The owner's manuals for some MYs do not show LAs for the 2 <sup>nd</sup> row's center position. However, this model does have standard-spaced LAs in the center seating position, as indicated here.
--------------------------------------	-------	-------	-----------	-----	------	--



as of 02/09/2021

#### Page B-132, Kia

REASON FOR UPDATE: Correction to information provided for the 3<sup>rd</sup> row center seating position.

Revise the following information by replacing the struck-out text with the text in red.

TELLURIDE SUV (7- or 8- passenger)	20-21	<b>7-passenger:</b> None  <b>8-passenger:</b> N/A	(2) LATCH	<del>None</del> TA	Behind-driver: LATCH  Behind- passenger: None	( <del>3</del> 4) TAs on backs of seats <b>Seatback Angle:</b> Rotate seatback to a locked position that ensures good contact between the seatback and CR. <b>Seating Position Limitations:</b> Regardless of installation method, ensure that a CR does not contact or push against any seat belt buckle, as this can potentially damage the buckle.
---	-------	---	-----------	--------------------	--	---

***LATCH Manual Updates • 2021-2022***