LATCH Manual Update Related to Mitsubishi Outlander, 3-row, MY22 2021-2022 LM Updates Page, <u>www.saferidenews.com</u>

OUTLANDER 7-passenger SUV	07-20	ТА	(2) LATCH	N/A	None	 (3) TAs on backs of seats. Mitsubishi tethering tip: Turn the tether hook sideways, place it under the TA, and then rotate the hook (so the opening faces toward the bar) to hook it to the TA. Find TA photos at <i>www.saferidenews.com</i>, LATCH Gallery. 2nd Row: See "Seating position" bullet (above) for warnings. Head Restraints: Important to remove and securely stow the head restraint when a CR is installed (using any installation method); replace head restraint when CR is uninstalled. 3rd Row: Owner's manual says do not use this row for rearfacing CR installation. 2-Row Model: See table "Vehicles with one or two rows."
OUTLANDER 7-passenger SUV	22	ТА	(2) LATCH	N/A	None	 (3) TAs on backs of seats. Mitsubishi tethering tip: Turn the tether hook sideways, place it under the TA, and then rotate the hook (so the opening faces toward the bar) to hook it to the TA. Find TA photos at <i>www.saferidenews.com</i>, LATCH Gallery. Head Restraints: Important to remove and securely stow the head restraint when a CR is installed (using any installation method); replace head restraint when CR is uninstalled. Rear-Seat-Belt Reminder: A reminder icon signaling an unbuckled rear passenger may illuminate on the multi-information display when a CR is installed using LATCH. See owner's manual for details on preventing this false warning. Cargo Cover: See "Cargo covers" bullet (above) for guidance.